UNITED STATES DEPARTMENT OF THE INTERIOR MINERALS MANAGEMENT SERVICE GULF OF MEXICO REGION

NOTICE OF NEW FIELD DETERMINATIONS AND CHANGES IN EXISTING FIELDS JULY 2001

NEW PRODUCIBLE LEASES

LEASE	BLOCK	COMPANY	WELL	OIL/ GAS	DETERMINATION DATE	FIELI	NAME
G15271	EI 0397	W & T Offshore	e 1	Oil	01/22/01		EI380
G16224	WC 0661	Tarpon 0 & D	1	Oil	07/03/01	,	WC661*1
G16273	EC 0368	W & T Offshore	1	Gas	07/16/01	NEW	EC368
G16332	SM 0189	ATP O & G	1	Gas	07/10/01		SM175
G16363	EI 0268	Ocean Energy	1	Gas	05/23/01	NEW	EI268
G16673	GC 0004	W & T Offshore	2 1 ^{ST1}	Oil	01/23/01		EI380
G17804	WC 0464	W & T Offshore	8-A	Gas	07/11/01		WC464
G18921	GA 0418	W. G. Helis	1	Gas	07/02/01		GA418*1
G21056	WC 0459	Spinnaker	1	Gas	06/28/01		WC459*1
G21353	HIA0232	Samedan	A-1	Gas	05/31/01		HI244A
G21587	EC 0380	Walter O & G	SS001	Gas	07/03/01		GB065
G21614	SM 0035	Remington	1	Oil	06/07/01		SM023
G21680	ST 0274	Spinnaker	1	Gas	07/10/01	NEW	ST274

^{*1} Field is re-activated

FIELD DETERMINATION CHANGES AFFECTING ACTIVE LEASES

None

EXPIRED, RELINQUISHED, CONSOLIDATED OR TERMINATED LEASES

NOTE:

Lease G01201' SM 0069 was incorrectly terminated From SM073 Field in the May 2001 Notice. It is, in fact, still active.

Lease G01205, SM 0073 was incorrectly terminated From SM073 Field in the May 2001 Notice. It is, in fact, still active.

Lease G02551' WC 0537 was incorrectly terminated From WC537 Field in the September 2000 Notice. It is, in fact, still active.

Lease $G03569^{*2}$, EI 0294^{*2} was incorrectly terminated From EI294 Field in the **December 2000** Notice. It is, in fact, still active. Re-activate EI294 Field.

Lease $G03569^{*3}$, EI 0294^{*3} was incorrectly terminated From EI306 Field in the **December 2000** Notice. It is, in fact, still active.

Lease $G04397^{*4}$, WC 0291^{*4} was incorrectly terminated From WC165 Field in the May 2001 Notice. It is, in fact, still active.

Lease $G04397^{*5}$, WC 0291^{*5} was incorrectly terminated From WC187 Field in the May 2001 Notice. It is, in fact, still active.

Lease G10585, WC 0432 was incorrectly terminated From WC432 Field in the July 2000 Notice. It is, in fact, still active.

^{*2} N1/2

^{*3} S1/2

^{*4} N1/2; SW1/4; N1/2SE1/4

^{*5} S1/2SE1/4

REASSIGNMENTS OF EXPIRED LEASES

EXPIRED LEASE	AREA BLOCK	PRESENT FIELD NAME	NEW FIELD NAME				
G02713*6	HIA0562*6	HI562A	HI563A				
G05529	EI 0397	EI397	EI380				
G05529	GC 0004	EI397	EI380				
	DELETE EI397 FIELD						
G13436	HIA0562*6	HI562A	HI563A				
DELETE HI562A FIELD							

^{*6} SW1/4

J. Courtney Reed Chief, Reserves Section Resource Evaluation